Region 6 Sample Control Center, e-mail to [HYPERLINK "mailto:warren.christy@epa.gov"] or to [HYPERLINK "mailto:perez.myra@epa.gov"]

REQUEST FOR LABORATORY SAMPLE ANALYSES

Site Name: Lane Plating Works Inc. site	City/State: Dallas, Texas	CERCLIS #: TXN000605240			
GPRA Account #:2019 T 06L 303DD2 A6ASCO00	Site Spill ID# A6AS	Type of Investigation/Purpose: RI/FS			
EPA SAM, RPM, OSC: Kenneth Shewmake (RPM) Mail Code: 6SF-RA	Analytical Turnaround Time Region 6 Lab: 35_X_ CLP Organics: 7 14 21_X_ CLP Inorganics: 7 14 21 X_	Type of Contract: EPA RAC Contractor: Mark Paddack Direct: 972-315-3922 x 1214 Cell: 214-535-1844 Aaron Bugher Direct: 972-315-3922 x 1243 Cell: 405-642-1017			
		Shipping Contact: Mark Paddack and Aaron Bugher			
Telephone #: 214-665-3198	Are preliminary results required? 48 hrs VOA () Yes (X) No	Telephone #: see above			
Fax #:	72 hrs Extractables () Yes (X) No 72 hrs Inorganics () Yes (X) No	On Site Ph #:			
		E-Mail address: Mark Paddack [HYPERLINK "mailto:mpaddack@eaest.com"] Aaron Bugher [HYPERLINK "mailto:abugher@eaest.com"]			
(ਭ।ਹ) Potential Enforcement Action?	Requires justification and prior approval.	Date Sample Control Center Received Request For Sample Analysis:			
() Yes (X) No					
Proposed Sampling Period: week of May 27, 2019					

Please assure that this request for analytical services has been signed and dated by the appropriate Site Assessment Manager, Remedial Project Manager, or On Scene Coordinator. Please assure that the Sample Control Center has a copy of all relevant Quality Assurance Project Plans (QAPPs) and Sampling and Analysis Plans (SAPs).

Is the QAPP, QASP, SAP, O&M Plan, GWMP, DAW, or other relevant plan being submitted with this Request for Sample Analyses? If no, please explain (expected date of submission etc.): The SAP will be submitted prior to sampling.

Signature of EPA Site Assessment Manager (SAM), Remedial Project Manager (RPM), or On Scene Coordinator (OSC) to signify approval of this analytical service request.

To most efficiently obtain laboratory capability for your request, please address the following considerations. Incomplete or erroneous information may result in a delay in the processing of your request.

Signatu	ıre:		[Date:			
1.	General	description	of analytical	services	requested:	(QA/R5 -	Element B1)

Matrix	Analysis	•		C Samples
		(without QC) high/low conc	How many?	Type?
	Volatiles (Low)	1	1	Equipment Blank
Water			1	Trip Blank
			1	Duplicate
	Semivolatiles	1	1	Equipment Blank
			1	Duplicate
	Aroclor	1	1	Equipment Blank
			1	Duplicate
	Metals including mercury (total)	5	1	Equipment Blank
			1	Duplicate
	Dissolved Metals including mercury	5	1	Duplicate

Additional description (areas where samples are being collected etc.):

2. Analytical protocol required (analytical method & method number, extraction or digestion method & method number, CLP SOW reference, for each matrix if required, etc.): (QA/R5 - Element B4)

Current CLP methods (04/06/16) are: Organics by SOM02.4 and Inorganics ISM02.4

Matrix	Analysis	Methods		
	Volatiles	SOM02.4 Trace Water / Low Water		
Water	Semivolatiles	SOM02.4 Low Water		
	Aroclor	SOM02.4 Low Water		
	Metals, including mercury	ISM02.4/ICP-MS (with ICP-AES for salts only)		

Additional Information: [SEQ CHAPTER \h \r 1]

3. CLP Modified Analysis Clause - The latest Statement of Works (SOWs), includes a modified analysis clause. The modified analysis allows the regions to request minor changes to current SOW analytical methods in order to meet specific field site requirements. The changes are limited in scope and must be approved by the EPA CLP Program Manager and Contracting Officer before implementation. Information must be submitted <u>three weeks</u> prior to the sampling event. The information the client must submit three weeks prior to the sampling event are; Lab Request Form and the approved sampling plan/QAPP.

# of low	# of medium	Type of	# of low	# of medium

	conc. soils	conc. soils	Vials	conc. soils	conc. soils
Three 5-gram coring tool devices (e.g., EnCore) samplers					

4. Analytical results required (specify laboratory documentation and reporting requirements, reporting units, format requirements, etc.): (QA/R5 - Elements A6 and B4)

Standard CLP and/or EPA Region 6 Houston Lab deliverable

- 5. Data requirements (reporting limits; per analyte per matrix; reporting units; applicable reference levels, etc.): (QA/R5 Elements A7, B1, and B4) (Attach extra pages if necessary) For CLP capabilities http://www.epa.gov/superfund/programs/clp/facts.htm. For Region 6 Laboratory capabilities http://www.epa.gov/earth1r6/6lab/r6lab.htm
 - a. Compounds/chemicals of concern (Action levels etc.) Required information List the compounds/analytes driving the investigation and the action level required to meet DQO's.

Parameters	Action Levels/Detection Limits		
raidiffeters	Water (µg/L)		
Chromium	10		
Lead	10		
Mercury	0.2		
Cyanide	10		

.

6. QC Requirements (PE samples & frequency, spikes, duplicates, blanks, & frequency)

QC Type	Frequency	QC Limits
Trip Blank	1 per cooler containing aqueous VOC samples	
Duplicate	1 per 10	
Matrix Spike	1 per 20	